

Murata Power Solutions' 50mV and 100mV base-mounted current shunts are designed for measuring dc currents from 5A to 1200A. These precision shunts (+/-0.25% accuracy) connect directly to MPS's DCA5-20PC Series of dc ammeters. Installation is straightforward: simply connect the load circuit to the shunt's threaded studs and the shunt's mV Kelvin-outputs to the digital ammeter's input terminals.

All models feature a rugged phenolic base that provides 750V isolation to the shunt's brass terminals, allowing for direct attachment to metal surfaces. A highly stable (+/-15ppm/°C) manganin sensing-element provides a wide -40 to +60°C operating temperature range. Please see the DCA5-20PC data sheet for additional ammeter-related information and detailed connection diagrams.



| General Specifications (All Models) |                               |
|-------------------------------------|-------------------------------|
| Rated Accuracy                      | ±0.25% max.                   |
| Sensing Element                     | Manganin                      |
| Terminal Posts/Screws               | Brass                         |
| Tightening Torque                   | See Mechanical Dimensions     |
| Current Rating                      | See Selection Guide           |
| Operating Temperature               | -40 to + 60°C (-40 to +137°F) |

### Technical Notes

**IMPORTANT!** To ensure safe and reliable operation, dc shunts and all associated equipment must be installed and serviced by qualified technical personnel. Never make any connections to the shunt, the load, or the ammeter with energized power sources. Contact Murata Power Solutions if you have any questions regarding the installation or operation of any of our instruments and accessories.

**1. Base-Mounted Shunt Precautions:** DC current shunts are low value resistors that develop a mV output when current passes through their highly-stable manganin resistive element. Under high current, continuous use operation, dc shunts will dissipate considerable power and may undergo a significant temperature rise. For example, if allowed to operate continuously at its full rated load, a 500A/50mV shunt dissipates 25 Watts ( $500A \times 0.050V = 25 \text{ Watts}$ ). Therefore, whenever possible, be sure to specify 50mV shunts due to their inherently lower power dissipation and voltage drop.

To ensure that the manganin sensing element does not exceed 125°C under worst case operating conditions, please read and follow the guidelines in the mounting and derating sections of this data sheet. Tighten all connections on the shunt per the torque specifications given in the mechanical dimensions and selection guide on page 3. Please note, the user is responsible for selecting the correct wire sizes (gauge) and wire type for the given application.

**2. Mounting Considerations:** All shunts should be mounted with their resistance blades in a vertical position to allow for natural convection cooling (see Figure 1). Forced-air cooling must be provided when vertical mounting is impractical, or in installations where the shunt is installed in a confined location. The shunt's manganin blades must never be allowed to exceed +125°C; doing so will cause permanent damage to the shunt.

Shunts must be installed in a manner that protects them from damage due to thermal expansion forces produced by high- or short-circuit currents. In most cases, shunts are weaker than their external-circuit connections, so provisions for additional wiring-flexibility may be required in high current and/or high-vibration applications.

Whenever practical, all shunts should be connected in the grounded side (normally the 'chassis') of the dc supply. However, these shunts must be connected in the grounded side of the circuit when the dc supply exceeds 750 volts (the rated limit for the shunt's phenolic insulating base). When more than one wire is to be connected to each end of a shunt, the wires must be evenly distributed between both terminals (see Figure 1).



Figure 1. Typical installation






### MECHANICAL SPECIFICATIONS

#### 5 through 150 Amps

| Part No.     | Rated Current/Output | Resistance (Ωs at 25°C) | Torque Range             |
|--------------|----------------------|-------------------------|--------------------------|
| 3020-01097-0 | 5A/50mV              | 0.01                    | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01107-0 | 10A/100mV            | 0.01                    | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01098-0 | 20A/50mV             | 0.0025                  | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01096-0 | 50A/50mV             | 0.001                   | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01099-0 | 100A/50mV            | 0.0005                  | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01108-0 | 100A/100mV           | 0.001                   | 36-40 in-lbs (4.1-4.5Nm) |
| 3020-01100-0 | 150A/50mV            | 0.00033                 | 36-40 in-lbs (4.1-4.5Nm) |


8-32 Kelvin output screws (all shunts): 14-15 in-lbs (1.58-1.69Nm)



#### 200 through 500 Amps

| Part No.     | Rated Current/Output | Resistance (Ωs at 25°C) | Torque Range               |
|--------------|----------------------|-------------------------|----------------------------|
| 3020-01101-0 | 200A/50mV            | 0.00025                 | 14-15 ft-lbs (19.0-20.3Nm) |
| 3020-01102-0 | 300A/50mV            | 0.000167                | 14-15 ft-lbs (19.0-20.3Nm) |
| 3020-01103-0 | 500A/50mV            | 0.0001                  | 14-15 ft-lbs (19.0-20.3Nm) |


8-32 Kelvin output screws (all shunts): 14-15 in-lbs (1.58-1.69Nm)



**MECHANICAL SPECIFICATIONS** *(continued)*

| 800 through 1200 Amps |                      |                         |                            |
|-----------------------|----------------------|-------------------------|----------------------------|
| Part No.              | Rated Current/Output | Resistance (Ωs at 25°C) | Torque Range               |
| 3020-01104-0          | 800A/50mV            | 0.0000625               | 32-35 ft-lbs (34.4-47.5Nm) |
| 3020-01105-0          | 1000A/50mV           | 0.00005                 | 32-35 ft-lbs (34.4-47.5Nm) |
| 3020-01106-0          | 1200A/50mV           | 0.0000417               | 32-35 ft-lbs (34.4-47.5Nm) |

8-32 Kelvin output screws (all shunts): 14-15 in-lbs (1.58-1.69Nm)





Компания «ЭлектроПласт» предлагает заключение долгосрочных отношений при поставках импортных электронных компонентов на взаимовыгодных условиях!

Наши преимущества:

- Оперативные поставки широкого спектра электронных компонентов отечественного и импортного производства напрямую от производителей и с крупнейших мировых складов;
- Поставка более 17-ти миллионов наименований электронных компонентов;
- Поставка сложных, дефицитных, либо снятых с производства позиций;
- Оперативные сроки поставки под заказ (от 5 рабочих дней);
- Экспресс доставка в любую точку России;
- Техническая поддержка проекта, помощь в подборе аналогов, поставка прототипов;
- Система менеджмента качества сертифицирована по Международному стандарту ISO 9001;
- Лицензия ФСБ на осуществление работ с использованием сведений, составляющих государственную тайну;
- Поставка специализированных компонентов (Xilinx, Altera, Analog Devices, Intersil, Interpoint, Microsemi, Aeroflex, Peregrine, Syfer, Eurofarad, Texas Instrument, Miteq, Cobham, E2V, MA-COM, Hittite, Mini-Circuits, General Dynamics и др.);

Помимо этого, одним из направлений компании «ЭлектроПласт» является направление «Источники питания». Мы предлагаем Вам помощь Конструкторского отдела:

- Подбор оптимального решения, техническое обоснование при выборе компонента;
- Подбор аналогов;
- Консультации по применению компонента;
- Поставка образцов и прототипов;
- Техническая поддержка проекта;
- Защита от снятия компонента с производства.



#### Как с нами связаться

**Телефон:** 8 (812) 309 58 32 (многоканальный)

**Факс:** 8 (812) 320-02-42

**Электронная почта:** [org@eplast1.ru](mailto:org@eplast1.ru)

**Адрес:** 198099, г. Санкт-Петербург, ул. Калинина, дом 2, корпус 4, литера А.